

How to Maintain Your Shower So That It Looks and Lasts

General Shower Stall Cleaning

Pour CRL "Concentrated Glass Cleaner" in a spray bottle and apply liberally on the tile and shower surfaces. A simple scrub and rinse done weekly will keep your shower sparkling.

Preventing Build Up of Soap Scum and Mineral Deposits

Apply a coat of CRL Crystal Shield to prevent build up of lime deposits on the glass. This coating will last up to a year. Rubbing on lemon oil also prevents build up of soap scum but the hot water washes off the oil quickly.

Removing Soap Scum and Mineral Deposits from Glass

Use CRL "Spot and Water Stain" remover to remove stubborn stains.

Cleaning Frameless Shower Hinges and Hardware

Use soap and hot water on a non-abrasive cloth.

Copyright © 2005 Artistcraft Shower Doors No reproduction without permission <u>www.artistcraft.com</u>